

NORTHWEST MOUNTAIN REGION RUNWAY INCURSION ACTION TEAM VISIT

King County International Airport /
Boeing Field
May 24, 2001

Jim Greene

Regional Runway Safety Program Manager

Northwest Mountain Region Federal Aviation Administration



Definition of Runway Incursion

Any occurrence at an airport involving:

- an aircraft
- a vehicle
- a person
- or an object

on the ground that creates a collision hazard or results in loss of separation with an aircraft taking off, intending to take off, landing, or intending to land.



Sedan versus DC-10






Runway Incursion Types

Runway incursions result from three types of surface incidents:

- Operational Errors (OE)
- Pilot Deviations (PD)
- Vehicle/Pedestrian Deviations (V/PD)




Trends




431 Runway Incursions During CY 2000



Trends - Incursions by type









Top Incursion Airports

CY 2000

LOCATION	LOC ID	OPS	RI	RATE
North Las Vegas Arpt, NV	VGT	229,703	16	6.97
Montgomery Field/San Diego, CA	MYF	260,235	9	3.46
Fort Lauderdale Exec, FL	FXE	263,359	9	3.42
Merrill Field, Anchorage, AK	MRI	201,148	8	3.98
Long Beach Arpt, CA	LGB	416,766	8	1.92
Logan Arpt, Boston, MA	BOS	512,985	8	1.56
Los Angeles, CA	LAX	786,421	8	1.02
Jeffco Arpt, Denver, CO	BJC	177,319	7	3.95
Concord Arpt, CA	CCR	212,112	7	3.30
Orange Co/John Wayne Arpt, Santa Ana, CA	SNA	405,473	7	1.73
Santa Barbara, CA	SBA	163,865	6	3.66
Lambert Fld, St. Louis, MO	STL	490,779	6	1.22
Phoenix Sky Harbor Arpt, AZ	PHX	632,360	6	0.95
Troutdale Arpt, OR	TTD	76,252	<mark>5</mark>	6.56
Teterboro Arpt, NJ	TEB	272,201	5	1.84



Top Incursion Airports

CY 2000

LOCATION	LOC	OPS	RI	RATE
San Jose Arpt, CA	SJC	300,365	5	1.67
Bridgeport, CT	BDR	90,760	4	4.41
Greater Rockford Arpt, IL	RFD	94,571	4	4.23
McGhee Tyson Airport Knoxville, TN	TYS	152,330	4	2.63
Providence, RI	PVD	157,470	4	2.54
Sarasota/Bradenton Arpt, FL	SRQ	174,515	4	2.29
Palwaukee Muni, Chicago, IL	PWK	185,236	4	2.16
Albuquerque, NM	ABQ	233,632	4	1.71
Midway Arpt, Chicago, IL	MDW	303,192	4	1.32
Salt Lake City, UT	SLC	370,681	<mark>4</mark>	1.08
San Francisco, CA	SFO	437,186	4	0.92
Newark, NJ	EWR	461,457	4	0.87
Cincinatti-Covington Arpt, OH	CVG	486,590	4	0.82
O'Hare, Chicago, IL	ORD	914,131	4	0.44



Sweeper versus DC-9





RISK ASSESSMENT



Why We Assessed Data

- As a result of feedback from 2000 Summit, needed to place runway incursions into another context
- Need a better way to track incursions
- Need a better understanding of where incursions happen
- Need a way to analyze data to get at causal factors
- Need to describe clearer picture of runway incursion incidents *Not every incursion is a Tenerife*



What Was Done

- Formed a team of "experts" to assess incursions in detail
- Developed four runway incursion categories coordinated with ASD and other agency analysis activities (Dr. A. Barnett)
- Mitre and NASA ASRS observed and validated the process



Definitions

- A Separation decreases to a point where the margin of safety is so low that the participants <u>barely avoid a collision</u>.*
- BSeparation decreases to a point where a <u>significant</u> potential for a collision existed.
- Separation decreases, or the potential for separation to decrease exists, <u>but ample time and distance exist</u> to avoid a potential collision.
- Described Descri

^{*} The data contained in category A includes all accidents that occurred as a result of runway incursions (1997-2000), one in LaGuardia, NY & one in Sarasota, FL.



Assessment Process

Evaluated over 1350 incidents – all incursions during 1997 – 2000 – *one at a time*

- Projected airport diagram
- Projected all reported incident information
- "Walked-thru" incident and discussed event
- Reached Team consensus and assigned collision risk category (A-D)
- Asked 20+ questions for every incident to collect additional data
- Marked incident location on airport diagram




Additional Details Now Available

- Airport
- Date & Time
- Incursion Type
- Operation Type
- Callsigns
- Type Aircraft
- Phase of Flight
- Combined Positions
- Construction

- Foreign Carrier
- Non-Pilot
- Vehicle Type
- LAHSO
- Intersecting Runways
- Confusing Intersection
- Low Visibility
- Training (pilot/controller)
- Hold Short




National Runway Incursion INCIDENTS






REGIONAL Runway Incursion INCIDENTS 1997 - 2000






Northwest Mountain Region Runway Incursion RATE







Northwest Mountain Region Runway Incursion INCIDENTS











Primary Causes of Runway Incursions

- Breakdown in Pilot/Ground
 Vehicle/Controller Communications
- Lack of Airport Familiarity
- Loss of Situational Awareness



What Happened with My Suggestion?

- Nearly 1,000 recommendations from:
 - Regional Workshops / National Summit
 - •NTSB / JSAT / GAO /aviation industry; etc
- Rolled up' into 50 larger solutions
- Ten Action Items for fast track implementation

Became the TOP TEN



- 1. Enhanced Operational Tower Controller Training
 - LOB: Air Traffic
 - Modify existing OJT training course to place a higher priority on maintaining situational awareness and prioritization when applying anticipated separation
 - Computer Based Instruction-Develop Runway Incursion specific training to be administered prior to local control certification and establish recurring training requirements.
 - Status: Finalizing workgroup participants with NATCA



- 2. <u>Foreign Air Carrier Pilot Training, Education</u> and Awareness
 - LOB: Flight Standards
 - Program to increase awareness and prevention of RIs within international aviation community
 - Two Tasks:
 - Develop fast process for inspectors to determine a pilot's level of English proficiency
 - Identify a process that will help foreign air carriers to achieve a 50% + compliance with level2 English proficiency (2002 2005)
 - Status: Focal point (Bob Hall DFW) is assembling team from IFOs, contractors, and ICAO to establish charter. Action plan expected 2/01.



- 3. <u>Advisory Circular for Airport Surface</u> <u>Operations</u>
 - LOB: Flight Standards
 - Standard operating procedures for airport surface operations. Applicable to Part121,129, 125, 135, and 91 operators. Covers cockpit issues such as planning, situational awareness, techniques for transiting complex intersections, intra-cockpit coordination and communications with ATC.
 - Status: Completed and signed by AFS-1. Currently in Federal Register for 30 day comment period. AC will be published after reviewing comments at the end of the 30 day period.



4. Airport Markings

- LOB: Airports
- Increase the visibility of runway hold line markings. Change existing A/C to require double-sized markings (outlined in black with glass beads) at all certificated and towered airports.
- Status: Change to AC has been accomplished







- 5. Education, Training, and Awareness for Pilots, Controllers, and Vehicle Operators
 - LOB: ATS-20
 - Develop a resource library of RI materials available at RSP Web Site and linked to other aviation safety sites.
 - Status: Final workgroup was conducted December 5, 2000. Estimated completion date is March 30, 2001.



6. Memory Enhancement Techniques for Tower Controllers

- LOB: Air Traffic
- Techniques to enable tower controllers to manage working memory more effectively
- Status: Finalizing workgroup participants with NATCA



- 7. Pilot Controller Phraseology Review
 - LOB: Air Traffic
 - A comprehensive assessment of required pilot controller surface operations phraseology. Objective is to reduce communications workload by condensing, modifying, or eliminating verbiage. Includes harmonizing phraseology with ICAO.
 - Status: Finalizing workgroup participants with NATCA.



- 8. Improved Pilot Evaluation and Testing
 - LOB: Flight Standards
 - Evaluate ground operations performance and test for knowledge of signs, lighting, and marking during all initial certification check flights. Flight instructors and Designated Pilot Examiners will test surface operations knowledge during recurrent evaluations.
 - Status:
 - Airline Transport Pilot and Certified Flight Instructors
 Practical Test Standards have been modified
 - Private, Commercial, and Instrument Practical Test Standards are in the process of being modified
 - Projected completion expected by end of June 01



- 9. Air Traffic Teamwork Enhancement (ATTE)
 Training for Tower Controllers
 - LOB: Air Traffic
 - Conduct ATTE training at 10 facilities that have the highest number of RIs resulting from operational errors.
 - Status: Finalizing workgroup participants with NATCA

ATTE Facilities: BOS, BUR, DFW, LGA, MDW, MKE, PBI, SFO, SJC, & TEB



- 10. Technology Assessment
 - The FAA has a number of technology programs underway aimed at improving runway safety. They include the following:
 - Airport Surface Detection Equipment, Model 3 (ASDE-3)
 - Airport Movement Area Safety System (AMASS)
 - Airport Surface Detection Equipment, Model X (ASDE-X)



• 10. Technology Assessment Continued

- Safeflight 21 (SF-21)
- ●In addition, the FAA issued a Broad Agency Announcement (BAA) seeking proposals for new and emerging runway safety technologies.



Snow Plow versus Wingtip







Runway Safety Program

www.faa.gov/runwaysafety















ANM Points of Contact

(ANM Runway Safety Team)

- Runway Safety Program Manager, ANM-1R, Jim Greene, (425) 227-1369 Jim.k.greene@faa.gov
- Airports Division, ANM-600, Mark Taylor, (425) 227-2625 Mark.taylor@faa.gov
- Flight Standards, ANM-200, Mary Hoy, (425) 227-2262 Mary.Hoy@faa.gov
- Airway Facilities Operations, ANM-400, Willie Eigner, (425) 227-2336 Willie.eigner@faa.gov
- Air Traffic Control, ANM-500, Don Bringmann, (425) 227-2550 Donald.bringmann@faa.gov We Listen....

We Respond



Pickup Truck versus B-747






Local Problems require local Solutions

Recent Data for King County International Airport

RUNMAL

POMINISTRA








A THE PARTY OF THE TOWER CLEARANCE REQUIRED









Local Problems require local Solutions

Airport Traffic Control Tower

King County International Airport